

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

123
P.
T-13

CORNERS OF THE PUBLIC SURVEY

T. 2. 145 N. R. R. 27 W. 5 th Mer.

1/4 cor. Corner common to Sections
27, and 28

Corner consists of a wood stake in place
State condition fair

Dimensions above ground 3 feet high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	I/4	I/4	
S		S	

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

I/4 S 27			

Species Cedar

Diameter 8 "

Bearing N 55 E

Distance 7 lks.

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why?


S. M. Hanley
(Signature)
Chief of Party

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this
 ----- chains distant.
 from which this Corner bears
 side of -----
 tree ----- inches diameter, on the
 Metal Location Poster is on a -----



(Make sketch of topography near Corner)

T. 145 N. R. 27 W. S. 17. Mer.