

Form 874-S—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P

Chippewa NATIONAL FOREST P-13

CORNERS OF THE PUBLIC SURVEY

T. 145N. R. 27W. 5th P. Mer.

Quarter Corner common to Sections
.....,, 21, and 22

Corner consists of a scribed Post (not) in place


State condition Fair. Set new Post.

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam. Dead

Diameter 3"

Bearing S 12° E.

1/5 Distance 30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Gjelhaug

(Signature)

Jr. Civil Eng.

(Title)

4/23/37
(Date)

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.52

from which this Corner bears N25°W.

side of tree

tree 3 inches diameter, on the North

Metal Location Poster is on a *Tree*.



(Make sketch of topography near Corner)

T. 145N. R. 27W. 5th P. Mer.