

U. S. Department of Agriculture
FOREST SERVICE

W-14

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5^d Mer.

1/16 Corner common to Sections

34, _____, _____, and _____

Corner consists of a metal peg (set) in place


State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____


Do you believe this to be a genuine Land Office Corner? Yes

If not, why? no evidence

Stanley M. Morrison
(Signature)

11/20/58
(Date)

Forestry Aid
(Title)



(Make sketch of topography near Corner and show section line markers with "X")

Metal Location Poster is on a Bush

tree 3 inches diameter, on the East

side of tree

this Corner bears N, 25 degrees Christmas

Section line marker between Secs. _____ and _____ is on

a _____ on the _____

located _____

chains L, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. _____

(Cross out nonapplicable)

Give any further facts needed to find Corner again: _____
