

U. S. Department of Agriculture
FOREST SERVICE

V-14

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5^a Mer.

1/16 Corner common to Sections
34, _____, and _____

Corner consists of a metal cap (mat.) in place


State condition Good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? no evidence

Stanley M. Morrison

(Signature)


Forestry aid

(Title)

11/20/59
(Date)

T. 145 R. 27 Mer. 52

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Tomato* tree 7 inches diameter, on the *South* side of *Map*

this Corner bears *N 60° W* from which *20* chains

Section line marker between Secs. and (Bearing) (Distance)

is on the (Name of road, trail, etc.)

located (Tree, post, etc.) chains E., W., N., S., from Sec. Cor.; 1/4 Cor.; Witness Cor.

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

Block in corner of
3rd and 4th