

U. S. Department of Agriculture
FOREST SERVICE

U-14

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5th Mer.

1116 Corner common to Sections
27, _____, _____, and _____

Corner consists of a square slab (net) in place



State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? no evidence

Stanley M. Morrison
(Signature)

11/20/54
(Date)

Forestry aid
(Title)

Metal Location Poster is on a *Iron nail*
 tree *7* inches diameter, on the *West* side of
 this Corner bears *0*° (Bearing) (Distance) Chains.
 Section line marker between Secs. and is on
 a *0* on the (Tree, post, etc.)
 located chains *L, W, N, E,* from Sec. Cor.; $\frac{1}{4}$ Cor.; Witness Cor.
 (Cross out nonapplicable)
 Give any further facts needed to find Corner again:
Blue line located N. from corner



(Make sketch of topography near Corner and show section line markers thus "X")
 T. 145 R. 27 Mer. *50*