

U. S. Department of Agriculture  
FOREST SERVICE

T-14

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 175 R. 27 5<sup>th</sup> Mer.

1/16 Corner common to Sections  
27, \_\_\_\_\_, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a metal toy (rust) in place


State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? no evidence

S. M. Morrison

(Signature)

11/20/54


(Date)

Forestry and

(Title)

T. 145 R. 27 S. 2 Mer.

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Black spruce* tree 9 inches diameter, on the *South* side of *the* this Corner bears \_\_\_\_\_ (Bearing) \_\_\_\_\_ (Distance) Chains. Section line marker between Secs. \_\_\_\_\_ and \_\_\_\_\_ is on a \_\_\_\_\_ on the \_\_\_\_\_ (Tree, post, etc.) \_\_\_\_\_ (Name of road, trail, etc.) located chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: *Blue line poster N.B.S. corner*

-----  
 -----  
 -----  
 -----  
 -----  
 -----