

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

32

123

Chippewa NATIONAL FOREST V-15

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 5 Mer.

1/4 Corner common to Sections
27, and 34

Corner consists of a wooden stake (~~post~~) in place
State condition Partial rotten & green lines

Dimensions above ground 56 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|------------------------|--|------------------------|--|
| <u>1/4</u> <u>5</u> | | <u>1/4</u> <u>5</u> | |
| <u>27</u> | | <u>34</u> | |

| | | | |
|--|--|--|--|
| | | | |
| | | | |

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--------------|--|--|--|
| <u>Blaze</u> | | | |
| | | | |

Species Species

Diameter 10"

Bearing N 41° E

Distance 79 1/4

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Brill

(Signature)

Chief of Party


(Title)

7/6/34

(Date)

Corner again.
Place this point to east of W. 2
from corner 10/9/59 by A. H. ...
at my ... from - ...
at ... place

Metal Location Poster is on a *Advance*
tree 2 inches diameter, on the *W. 2*
side of *tree*
from which this Corner bears *5*
6 ~~feet~~ *feet* distant.



(Make sketch of topography near Corner)