

Form 874-9—Revised May, 1918
 U. S. DEPARTMENT OF AGRICULTURE
 FOREST SERVICE

Posted

Chippewa NATIONAL FOREST E-16

CORNERS OF THE PUBLIC SURVEY

T. 145N. R. 27W. 5th Mer.

E 16 Corner common to Sections
 _____, 3, and 10

Corner consists of a squared stake in place
 State condition 1st slightly rotten at base

Dimensions above ground 2 X 2 X 60' inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

$\frac{1}{16}$ S		$\frac{1}{16}$ S	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{16}$ S	Forest Service Marker		
B.T.			

Species Tam stub Tam

Diameter 5" 3"

Bearing S 87° W N. 35° W

Distance 6 lbs. 13 lbs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. A. Bills
Edward

Signature.

12/13/33

10-16-29


Estimator

Date.

Title.

(Make sketch of topography near Corner.)

T. 145 N R. 27 W S. 22 Mer.



Metal Location Poster is on a Tamack Tam.
 tree 2.3" inches diameter, on the North S.E.
 side of Section line Tamack.
 from which this Corner bears N. 48° W. S. 35° E.
 . 23 1/3 kts. chains distant.

Give any further facts which will aid in finding this
 Corner again.

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Mer.

E 1/2 Corner common to Sections

3, and 10 post

Corner consists of a 2x3 scribed post in place

State condition POOR

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION






N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *tan stym* *tan stym*

Diameter 44 rotten 7 8

Bearing N89°W N41°W S90°E

Distance 3.9' 15.1' 19.2'

Do you believe this to be a genuine Land Office Corner?

If not, why? NO

orig survey

4-15-58

(Date)


(Signature)

(Title)

CORNER OF THE GUNTO SURVEY

Corner again.
I blazed line N to trail
and put post on

Give any further facts which will aid in finding this
corner distant.
151 ft
from which this corner bears
541° E
side of
tree 7 inches diameter, on the
5 ft
tam. Metal Location Poster is on a



(Make sketch of topography near corner)

T. 145 R. 27
Mer. E-16

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

123
 ER6

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 27 W. 6 Mer.

$\frac{1}{16}$ Corner common to Sections
 3, and 10



Corner consists of a Wooden stake (not) in place
 State condition slightly rotten at base

Dimensions above ground 60 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Dead hemlock Temperate _____

Diameter 5" 3" _____

Bearing W N 35° W _____

Distance 4 links 13 links _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. A. Brittle

(Signature)

12/13/33

(Date)

ECC Surveyors
Chicago, Ill.

Corner again.

Give any further facts which will aid in finding this


1317 ft. - oblique distant.

from which this Corner bears S 35° E

side of Samarok

tree 3 inches diameter, on the S.E.

Metal Location Poster is on a Samarok



(Make sketch of topography near Corner)

T. 146 N. R. 22 W. Mer. 5