

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

W-M

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5th Mer.

North ~~South~~ 1/6 Corner common to Sections
34, and 35

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

N 7 W
S. 34 D. T.

--

--

--

F. S. M.

--

--

--

Species Stump _____

Diameter 8" _____

Bearing Face on _____

Distance N.E. side _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


H. A. Bills
(Signature)

Chief of Party
(Title)

2/2/34
(Date)

Corner again.
F.S.M. on road approx. 8 chs.
south of R.T.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears *No. corner.*
side of *stump.*
tree *8* inches diameter, on the *N.E.*
Metal Location Poster is on a *stump*



(Make sketch of topography near Corner)

T. 145 R. 27
5th Mer.

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted
W-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *195* R. *27 W.* *5th* Mer.

Wander Corner common to Sections
34 and *35*

DESCRIPTION OF CORNER


Corner consists of a *None left*

Dimension above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing *SW* _____

Distance _____

T 145 N
R 27 W
S 34
BT
9"
SW

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

[Signature]
Signature

[Title]
Title


9-12-29

Date.

Title.

T. 14 S. R. 29 W. S. Mer.

3-3037 (Make sketch of topography near Corner.)



Metal Location Poster is on a *Down*
 tree *9* inches diameter, on the *side of*
 from which this Corner bears *down*
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.
Distance is about
90 links N. of a stake
1 mile long & 1/2 mile
W.