

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*Posted*  
**E-17**

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5th Mer.

Section Corner common to Sections

2, 3, 10, and 11

Corner consists of a Scribed Squared stake (not) in place



State condition Fair

Dimensions above ground 4x4x48 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of ✓ is located ✓

✓ Pits are located ✓

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Red Oak

Diameter 5"

Bearing N11°W

Distance 60ln

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

*Edward Jensen*

Signature.

10-23-29

Date.


Estimator

Title.

T. 145 N. R. 27 W. S. 4 Mer.

8-3027

(Make sketch of topography near corner.)



Metal Location Poster is on a spruce

tree 8 inches diameter, on the south

side of E.W. Sec. line

from which this Corner bears  $N 73^{\circ} E.$

chains distant.

Give any further facts which will aid in finding this

Corner again.