

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Posted
 123
 A-17

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 27W 5th P. Mer.

145

Section Corner common to Sections

35, 34, 2, and 3

Corner consists of a Squared Stake (not) in place

State condition Part left. No scribing (replace

Dimensions above ground 4" diameter inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

SW/SW Sec. 3	SE/SE Sec. 3	NE/NE Sec. 3	NW/NW Sec. 2	NW/NW Sec. 2	SE/SE Sec. 3
NW	SW	SE	SE	SE	E

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S ^J	S	burned off	
	B.T.		

Species	8	8	8
Diameter	24"	20"	22"
Bearing		S78°E	S13°30'W
Distance	.24 ch	1666 ch.	

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

(Signature)

(Date)

(Title)

Corner again. Give any further facts which will aid in finding this


1.66 ch chains distant.

from which this Corner bears N78°W

side of Bearing Tree

tree 20" inches diameter, on the NW

Metal Location Poster is on a Norway Pine



(Make sketch of topography near Corner)