

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

CHIPPEWA NATIONAL FOREST

123
L-18

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 27 S. 5 Mer.

1/16 Corner common to Sections

14, and

Corner consists of a **Wooden stake** in place

State condition **rotten at ground line**

Dimensions above ground 42 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/16</u> S		<u>1/16</u> S	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16</u> S			
<u>BT</u>			

Species Spruce

Diameter 3"

Bearing N9°E

Distance 10 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. G. Boyle
(Signature)

5/29/34
(Date)

Chief of party
(Title)

*Proctor by B. W. 1/15 1938 F-1
London Lane Ave. 14
London and 7-18 1/2 from corner*

East and West.

Well placed and brushed line North.

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)