

U. S. Department of Agriculture

FOREST SERVICE

12

123

CHIPPEWA NATIONAL FOREST

A-19

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 6 Mer.

1/4

Corner common to Sections

23

14

and

Corner consists of a wooden stake (not) in place


State condition Rotten at ground line

Dimensions above ground 60 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tamarack

Diameter 10"

Bearing S 86' E.

Distance 1 chain

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Brill

(Signature)

5/29/34

(Date)

Chief of Party

(Title)

Metal Location Poster is on a **10** inches diameter, on the **West** side of **tree** from which this Corner bears **North 86° West** **1** chains distant.

Give any further facts which will aid in finding this Corner again.

|             |             |             |             |
|-------------|-------------|-------------|-------------|
| <p>Sec.</p> | <p>Sec.</p> | <p>Sec.</p> | <p>Sec.</p> |
| <p>Sec.</p> | <p>Sec.</p> | <p>Sec.</p> | <p>Sec.</p> |

(Make sketch of topography near Corner)

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*Posted*  
N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 27W 5 Mer.

1/4 Corner common to Sections

14, 23, and

Corner consists of a scribed stake (not) in place

State condition good

Dimensions above ground 2" x 2" x 36" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|            |                                     |            |                                     |
|------------|-------------------------------------|------------|-------------------------------------|
| <u>1/4</u> | <input checked="" type="checkbox"/> | <u>1/4</u> | <input checked="" type="checkbox"/> |
| <u>5</u>   |                                     | <u>5</u>   |                                     |
| <u>14</u>  |                                     | <u>23</u>  |                                     |

|                                     |                                     |                                     |                                     |
|-------------------------------------|-------------------------------------|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
|                                     |                                     |                                     |                                     |
|                                     |                                     |                                     |                                     |

N W S E NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|                 |                                     |                                     |                                     |
|-----------------|-------------------------------------|-------------------------------------|-------------------------------------|
| <u>F.S.M.P.</u> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
|                 |                                     |                                     |                                     |

Species T. tm.

Diameter 10" \_\_\_\_\_

Bearing S 86 E. \_\_\_\_\_

Distance 1 ch. \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

H. A. Brills


Chief of Party

5/29/34 Enil Juntunen  
Signature.

11/22/29 Batimaton  
Date. Title.

T. 145N R. 27W S Mer.

9-2027 (Make sketch of topography near Corner.)



Metal Location Poster is on a 10 Marack 10m.

tree 1310 inches diameter, on the E West side of N 5 1/2 tree

from which this Corner bears N 89° E N 56 B

11 chains distant.

Give any further facts which will aid in finding this

Corner again.

Edge of Jack Pine

1 chain East. IN SWAMP.