

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted
5-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5 Mer.

$\frac{1}{4}$ Corner common to Sections
11, 14, and

Corner consists of a scribed stake (not) in place
State condition good

Dimensions above ground 2" x 4" x 60" inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

$\frac{1}{4}$ S		$\frac{1}{4}$ S	
N	W	S	E

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ S	$\frac{1}{4}$ S	$\frac{1}{4}$ S	$\frac{1}{4}$ S
B.T.	B.T.		

Species	<u>TAM</u>	<u>TAM</u>	<u>dead</u>	<u>spruce</u>
Diameter	<u>2"</u>	<u>3"</u>	<u>3"</u>	<u>3"</u>
Bearing	<u>N51°W</u>	<u>S65°W</u>	<u>N45°W</u>	<u>S65°W</u>
Distance	<u>11 Links</u>	<u>14 Links</u>	<u>0.11</u>	<u>0.14</u>

Do you believe this to be a genuine Land Office Corner? yes


If not, why? _____

H. A. Brill
Chief of Party

4/16/34 B. H. Jentunen
Signature.

11/14/29 Estimator
Date. Title.

Metal Location Poster is on a tree _____ inches diameter, on the side of _____ from which this Corner bears _____ chains distant. Give any further facts which will aid in finding this Corner again.



9-3021 (Make sketch of topography near Corner.)

T. 145N R. 27W 5 Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

123
B-19

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Mer.

1/4 Corner common to Sections
11, and 14

Corner consists of a Wooden stake (not) in place
State condition Good

Dimensions above ground 74 inches inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

I/4 S		I/4 S	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

I/4S	I/4S		

Species dead spruce

Diameter 3" 3"

Bearing N45W 365W

Distance 0.14 0.14 chains

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

A. A. Brill

(Signature)

Chief of party


4/16/34

(Date)

(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

J-19

U. S. Department of Agriculture

FOREST SERVICE

J-19

Chippenaw NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5th Mer.

Corner common to Sections

11, and 14. Corner consists of a 3" two sided scribed Post (not) in place

State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NO BTs

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Corner believed to be put in by County Surveyor - (Check with him)

4-29-58

(Date)

(Signature)

(Title)

U. S. Department of the Interior
BUREAU OF LAND SURVEY

CORNERS OF THE PUBLIC SURVEY

Section _____ Township _____ Range _____


Corner again
Dial 300 to
East to
LINE 2445
Corner

Give any further facts which will aid in finding this

10.7 ft
From which this Corner bears

side of trees
feet
N 24 0 W

5 inches diameter, on the
Metal Location Poster is on a
NW 24 0 W



(Make sketch of topography near Corner)

T. 1140 B. 27 Mer. J-19