

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

P.
4-20

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5 th. Mer.

1/16

Corner common to Sections

26, _____, _____, and _____

Corner consists of a Wood stake (not) in place
State condition rotted off at gr. level

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/16</u>		<u>1/16</u>
	S		S

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16</u> S			

Species Larch

Diameter 4"

Bearing S 27 W

Distance 19 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

C. Gordon

Chief of party Et.

10-8-37

(Date)

(Title)

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a

<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>	<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>	<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>	<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>
<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>	<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>	<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>	<p>.....</p> <p>.....</p> <p>.....</p> <p>.....</p>



26

(Make sketch of topography near Corner)