

FORM 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Q-20

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5<sup>d</sup> Mer.

1/4 Corner common to Sections  
23, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a metal tag (not) in place

State condition good

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? no

If not, why? no evidence

6/24/59  
(Date)

Stanley M. Morrison  
(Signature)  
Forestry aid  
(Title)

Handwritten notes on the top section of the page, including "from corner" and "Also line from the south".

Corner again. Also line from the south from corner

Give any further facts which will aid in finding this


15 feet distant.

from which this Corner bears South

side of tree

tree 12 inches diameter, on the

Metal Location Poster is on a post



(Make sketch of topography near Corner)

T. 145N R. 27W S. 2 Mer.