

U. S. Department of Agriculture

FOREST SERVICE

4-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 5<sup>th</sup> Mer.

1/16 Corner common to Sections 25,           , and 26

Corner consists of a metal tag (not) in place



State condition good

Dimensions above ground            inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of            is located           

Pits are located           

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |

Species           

Diameter           

Bearing           

Distance           

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? no evidence

S. M. Morrison

(Signature)

Forestry and


(Title)

Sept. 1960  
(Date)

[Signature]  
Asst. D.F.R.

T. 145 R. 27 Mer. 5

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Post* tree 6 inches diameter, on the *Post* side of *Post* from which

this Corner bears (Bearing) (Distance) Chains. Section line marker between Secs. and is on a

(Tree, post, etc.) on the (Name of road, trail, etc.) located

chains L, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. Give any further facts needed to find Corner again: *Corner*

*Blk. line found S. 1/4 E. of*