

U. S. Department of Agriculture  
FOREST SERVICE

123  
P.  
5-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5 th Mer.

1/16 Corner common to Sections  
25, and 26

Corner consists of a two sided stake (not) in place  
State condition good

Dimensions above ground 48" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/16		1/16
	S		S


N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

*E. M. Handy*

(Signature)

Chief of Party

7/16/34


(Date)

(Title)

Metal Location Poster is on a tree ..... inches diameter, on the side of ..... from which this Corner bears ..... chains distant.

Give any further facts which will aid in finding this Corner again.

There is a PSIP on the section line 25 & 26 on the Mushka Trail.



(Make sketch of topography near Corner)

T. 145 N. R. 27 W. S. 5th. Mer.