

U. S. Department of Agriculture
FOREST SERVICE

R-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5th Mer.

Sec. 23 Corner common to Sections 23, 24, 25, and 26

Corner consists of a squared stake (not) in place
State condition good

Dimensions above ground 3" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S	S	S
23	26	25	24
T 145		R. 27	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Carl M. Handy

(Signature)

Chief of Party


(Title)

(Date)

Blazed lines running N. + N. of cor.
Corner again.

Give any further facts which will aid in finding this chains distant.

from which this Corner bears 5. Ch. 5.
side of stake
tree 4 inches diameter, on the W
Metal Location Poster is on a Larch



(Make sketch of topography near Corner)

T. 145 R. 27 Mer. 54