

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted
E-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5th Mer.

Section 12

Corner common to Sections

1, 2, 11, and 12

Corner consists of a Squared State (not) in place


State condition Down-Rotten

Dimensions above ground 4x4x50 inches.


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of ✓ is located ✓

✓ Pits are located ✓

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S
2

S
1

B.T.

B.T.

Species J. Pine

Diameter 9"

Bearing N75W

Distance 6 Lks

J. Pine

9"

N60E

2 Lks

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Edward Jensen

Signature.

10-25-24


Date.

Estimator

Title.

T. 145 N R. 27 W S. 25 Mer.

8-3027 (Make sketch of topography near corner.)



Metal Location Poster is on a *T. Pine*

tree 8 inches diameter, on the *west side*

side of *corner*

from which this Corner bears *S 89° W*

05 chains distant.

Give any further facts which will aid in finding this

Corner again.

Corner is about 104 South of a small

path hole of grass in the Birch stand

E-21

E-21

U. S. Department of Agriculture
FOREST SERVICE

----- NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Mer. 5

Section 10 Corner common to Sections
1, 2, 11, and 12

Corner consists of a (not) in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 2	
--------	--

--

S 1	
--------	--

--

old BT

--

old BT

--

Species J. Pine J. Pine - stub

Diameter 10" 10"

Bearing N 77° W N 7° E

Distance 4, 0' 13, 6'

Do you believe this to be a genuine Land Office Corner?

If not, why? Try 2 find orig stone

4-16-58

(Date)

(Signature)

(Title)

Metal Location Poster is on a _____
 tree _____ inches diameter, on the
 side of _____
 from which this Corner bears
 _____ chains distant.
 Give any further facts which will aid in finding this
 Corner again.

		Sec.	
		Sec.	

(Make sketch of topography near Corner)