

U. S. Department of Agriculture

FOREST SERVICE

4-22

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5<sup>th</sup> Mer.

1/16 Corner common to Sections 25, , and

Corner consists of a square stake (not) in place


State condition fair

Dimensions above ground 3 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

S. M. Morrison

(Signature)

Forestry and


(Title)

Sept. 1960 (Date)

W. E. [unclear] Asst. D.F.R.

T. 145 R. 27 S. 5 E. Mer.

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Cedar* tree 8 inches diameter, on the *west* side of

from which this Corner bears *W. 87°* (Bearing) and (Distance) Chains.

Section line marker between Secs. and is on a (Tree, post, etc.) on the (Name of road, trail, etc.)

located chains *1, 1/2, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50* from Sec. *5*; *1/2* Sec.; *1/4* Sec. (Cross out nonapplicable)

Give any further facts needed to find Corner again: *Blk. 1000 James St. E. S.W. of corner*