

U. S. Department of Agriculture

FOREST SERVICE

T-23

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5th Mer.


14
25 Corner common to Sections _____, _____, and _____

Corner consists of a metal tag (not) in place
State condition good

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No evidence

Stan C. M. Morrison

(Signature)
Forester and
(Title)

6/24/59
(Date)

Corner again. *See line from corner*


Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of *See*

tree *4"* inches diameter, on the *North* side. Metal Location Poster is on a *branch*



(Make sketch of topography near Corner)

T. 145 N. R. 27 W. S. 2 Mer.