

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

R-23

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W S. 2 Mer.

1/4 Corner common to Sections 24, and 25



Corner consists of a metal peg (not) in place State condition Good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence


Stanley M. Morrison (Signature)

Forestry and (Title)

6/24/19 (Date)

Corner again.
Please see poster sketch
from corner

Metal Location Poster is on a *tomato*
tree 8 inches diameter, on the *East*
side of *tree*
from which this Corner bears *East*
15 feet. *changes distant.*
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)