

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Q-23

NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 2nd Mer.

1/10 Corner common to Sections 24, _____, _____, and _____

Corner consists of a *metal* (not) in place
State condition *good*

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.




Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

14/6



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*


If not, why? *No evidence of real corner*

3/24/59
(Date)

S. M. Morrison
(Signature)
Forestry aid
(Title)

Corner again.
 Blue line for ~~the~~ west side of
 1/2 mile - corner on west side
 of camp of timber on corner
 from corner

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of tree
 tree 5 inches diameter, on the SE
 Metal Location Poster is on a post



(Make sketch of topography near Corner)