

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Posted
11/12/40
A-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 27W 5th P Mer.

1/4 Corner common to Sections
36, and 1

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/43</u> <u>36</u>			
<u>BT</u>			

Species Aspen

Diameter 18"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. M. Handy
(Signature)


1/12/40
(Date)

C. O. P.
(Title)

COMMENTS ON THE METRIC SURVEY

BT: 15' high on ground
Blazed line to corner

Corner again.
Give any further facts which will aid in finding this
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)