

U. S. Department of Agriculture  
FOREST SERVICE

4-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5<sup>th</sup> Mer.

4/6 Corner common to Sections  
25, , and


Corner consists of a Squared stake (not) in place  
State condition None

Dimensions above ground 2" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? X

If not, why? no evidence

S. M. Morrison


(Signature)

Forestry and

(Title)

Sept. 1960  
(Date)

T. 145 R. 27 S. 2 Mer.  
 (Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a cedar tree 8 inches diameter, on the North side of line from which this Corner bears N. 64° 00' (Bearing) and is on Section line marker between Secs. and is on a (Tree, post, etc.) on the (Name of road, trail, etc.) located chains E. W. N. S. from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable)  
 Give any further facts needed to find Corner again:  
*Blue line poster E. 70' corner*

-----  
 -----  
 -----  
 -----  
 -----