

U. S. Department of Agriculture

FOREST SERVICE

123

Chipewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N. R. 28W. 50P. Mer.

Quarter Corner common to Sections

20, and 33

Corner consists of an Oak Post (not) in place



State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J. Pinus

Mt. New N. Pine

Diameter 12

14

Bearing 91° E.

9.32 E.

Distance 40

30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Goltzang

(Signature)

1918 Jr. Civil Eng.


(Title)

V-11

SECTION 29
 SECTION 30
 SECTION 31
 SECTION 32
 SECTION 33

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



Make sketch of topography near Corner