

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ¹⁴⁵_{144 1/4} R. ²⁸₂₈ Mer. ^{5th}

----- Corner common to Sections

-----, ³⁴, and ³-----

Corner consists of a ^{yellow tag} (not) in place

State condition ^{good}-----

Dimensions above ground ^{54"}----- inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? ^{No}

If not, why? ^{No evidence found except oak tree which appears to have been removed on 4 sides.}

M. H. K. Saurter
(Signature)


^{8/6/59}
(Date)

Asst Dist Forester
(Title)

The corner is located on the
 east side of the corner
 of the section.

The corner is located on the
 east side of the corner
 of the section.

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree 10 inches diameter, on the SE
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 145 R. 28 Mer.