

Form 874-S—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

DP

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 28 W 5 Mer.  
Section Corner common to Sections  
34, and 35

Corner consists of a wood stake (not) in place  
State condition badly rotted

Dimensions above ground 2' high inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

FSLP			

Species Ash  
Diameter 8"  
Bearing S 34 W  
Distance 8 lks.

Do you believe this to be a genuine Land Office Corner?   
If not, why? no evidence of bearing trees and no scribing on stakes

C. Gordon

(Signature)  
C.O.P.

(Date)

(Title)


Form 100-1 (Rev. 1-25-50)

UNITED STATES DEPARTMENT OF AGRICULTURE

COMMENTS OF THE SURVEY PARTY

Other remarks:

Give any further facts which will aid in finding this corner from which this corner bears N 34 E side of said tree 8 inches diameter, on the North East Metal Location Poster is on a Asp



(Make sketch of topography near corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 28 5th Mer.

Sec. Corner common to Sections  
....., 34, and 35

Corner consists of a Wood stake (not) in place

State condition badly rotted

Dimensions above ground 2 ft. high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ..... is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>F.S.L.P.</u>			

Species Ash

Diameter 8"

Bearing S. 34 W.

Distance 8 lks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence of B.T. & no scribing on stakes.

C. Gordon

at party

(Date)

GOVERNMENT OF THE PUBLIC SERVICE

Corner again.

Give any further facts which will aid in finding this

8 It remains distant.

from which this Corner bears N 34 E.

side of tree

tree 8 inches diameter, on the N.E.

Metal Location Poster is on a 144-28 Ash

Sec 35	Sec 34
Sec.	Sec.

U. S. Department of Agriculture  
FOREST SERVICE

127

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 28 W 5 th. Mer.

Section Corner common to Sections

34, and 35

Corner consists of a wood stake (not) in place


State condition badly rotted

Dimensions above ground 2' high inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash

Diameter 8"

Bearing S 34 W

Distance 8 lks.

Do you believe this to be a genuine Land Office Corner? no.

If not, why? no evidense of bearing

trees and no scribing on stakes.

*C. Gordon*

Chief of party

(Date)

(Title)

Z-17

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

chains distant.

88

from which this Corner bears

N 34 E


side of said tree

tree inches diameter, on the

North East

Metal Location Poster is on a

Ash



(Make sketch of topography near Corner)

T. 145 N R. 28 W 5 th. Mer.

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 28 5th Mer.

Section corner Corner common to Sections

34, 35, 2, and 9

Corner consists of a yellow tan gravel stone in place


State condition good

Dimensions above ground 54 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Martin B. Rauscher


(Signature)

3/6/59 (Date)

Asst Dist For Ranger (Title)

Corner again.  
 old note to Andrew G. Allen  
 1902 - Log put up in road on  
 4th. Richard <sup>understanding</sup> ~~Richard~~ <sup>Richard</sup> ~~Richard~~  
 of corner.

Give any further facts which will aid in finding this  
 corners distant.  
 from which this corner bears *1 pm*  
 side of *tree*  
 tree *12* inches diameter, on the *NW*  
 Metal Location Poster is on a *Post*



(Make sketch of topography near Corner)