


E9 RE-9
Rotted

Meander Section Corners betw. Sec's 4 and 9

T 145N. R 30W. Mer. 51¹/₂



Corner is a Brass Capped Cement

Height 6" above Gr.

Dia 5"

Marked MC-S-9

BEARING TREES

MARKS	<u>MCS9</u>	<u>T.145NR30W.</u>	_____	_____
Species	<u>BT. ASH</u>	<u>BT. ASH</u>	_____	_____
Diameter	<u>6"</u>	<u>6"</u>	_____	_____
Bearing	<u>S.45W.</u>	<u>N.20E.</u>	_____	_____
Dist ^{ance}	<u>78 1/2 Ks.</u>	<u>65.1 Ks.</u>	_____	_____

Metal poster on _____

Remarks:

Date 12/18/33 Signed J.A. Gjelhaug

[The page contains extremely faint and illegible text, likely bleed-through from the reverse side of the document. The text is arranged in several paragraphs and is difficult to decipher due to low contrast and noise.]