

U. S. Department of Agriculture

FOREST SERVICE

posted
213

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145* R. *30* Mer.

Corner common to Sections

32, *33*, and *34*

Corner consists of a *Iron nail* (not) in place

State condition *Good*

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<i>S34</i>			<i>S33</i>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>7.57</i> <i>R. 30 W</i> <i>S34 SC</i>	<i>7.57</i> <i>P 30 W</i> <i>" "</i>		
<i>14.7</i>	<i>14.7</i>		

Species *Maple* _____

Diameter *8"* *7"* _____

Bearing *N 55° E* *N 43° W* _____

Distance *14.7* *14.7* _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Nov 14
(Date)

E. J. ...
(Signature)
Forester
(Title)