

U. S. Department of Agriculture
FOREST SERVICE

Posted

CHIPPewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. 5th Mer.

Quarter

Corner common to Sections

27, and 34

Corner consists of a Br. Cap Iron 1" (not) in place



State condition Good

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>5 27</u>	<u>1/4</u> <u>5 34</u>		
---------------------------	---------------------------	--	--

<u>B.T.</u>	<u>B.T.</u>		
-------------	-------------	--	--

Species Elm W. Oak

Diameter 8" 5"

Bearing N32°30'E S67°30'W

Distance 30.5 79.3

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

C. J. Mendenhall

(Signature)

Compassman

(Title)

8/28/34

(Date)