

U. S. Department of Agriculture  
FOREST SERVICE

X-17  
Posted  
X17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. 5th Mer.

Quarter Corner common to Sections  
39, and 35,


Corner consists of a Bur-capped pipe in place  
State condition good.

Dimensions above ground 10" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 539	1/4 539	1/4 935	
------------	------------	------------	--

Fallen

BT.?	B.T.	BT.?	
------	------	------	--

Species W. Pine W. Pine W. Pine

Diameter 20" 18" 24"

Bearing N70°W? N1°W N78°E

Distance 20 Lks. 80 96 3/4

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

D. G. Rose  
(Signature)

compassman  
(Title)

2/30/54.  
(Date)