

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. S. 5 Mer.

Section 34, 3, 2, and 35 Corner common to Sections

Corner consists of a Metal pipe (not) in place
State condition Good Capped

Dimensions above ground 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

34	3	2	35
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Sec 34</u>	<u>Sec. 3</u>	<u>Sec. 2</u>	<u>Sec. 35</u>
---------------	---------------	---------------	----------------

<u>B.T.</u>	<u>B.T.</u>	<u>B.T.</u>	<u>B.T.</u>
-------------	-------------	-------------	-------------

Species W. Oak W. Oak Aspen Aspen
Diameter 8" 7" 9" 4"
Bearing S52W S57W S25W N33 E
Distance 73' 43' 12' 73'

Do you believe this to be a genuine Land Office Corner Yes

If not, why? _____

W. Swift

(Signature)

(Date)


(Title)

Corner is located on Old Bens Road on the south side near the road.
Corner again.

Give any further facts which will aid in finding this

51 ~~XXXXXXXXXX~~
from which this Corner bears North East

52 6 inches diameter, on the North side of Pole
Metal Location Poster is on a Telephone pole



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

A17

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 + 146 N R. 30 W 5th Mer.
Section Corner common to Sections



2, 3, 34, and 35

Corner consists of a Br cap in concrete in place
State condition good

Dimensions above ground 6x4 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146N R30W S33	T146N R30W S34	T145N R30W SR	T145N R30W S3
B.T.	B.T.	B.T.	B.T.

Species Red Oak Aspen Aspen R. Oak
 Diameter 6" 6" 9" 6"
 Bearing N52°W N24°E S23½°E S47°W
 Distance 113½ 110 18 65

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

J. A. Gjelhaug

(Signature)

R-7-35
(Date)

by Tech. Eng. J. Sutton
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a No. poster



(Make sketch of topography near Corner)

Apr 17

5th

T1195146N R. 30W