

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

A-19



Chippewa NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY

T. 145-146 R. 30 5th Mer.

Quarter Corner common to Sections  
2, and 35

Corner consists of a Metal Cap (not) in place  
 State condition Good


Dimensions above ground 4 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
 CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J.P. J.P.

Diameter 6" 12"

Bearing N 72° W S 85° W

Distance 1.2 ch. 11 Ks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Harold Hennas  
 (Signature)

May 18, 1937  
 (Date)

Section 1

Section 2

Section 3

Section 4

Section 5

Section 6

Section 7

Section 8

Corner again.

Give any further facts which will aid in finding this


corner distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

8-19 M.G.

7145-46 R. 20

A-19

U. S. Department of Agriculture  
FOREST SERVICE

A19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145-146 R. 30 5th Mer.  
Quarter

Corner common to Sections  
2, and 35

Corner consists of a Metal cap (not) in place  
State condition Good

Dimensions above ground 4 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

35		2	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146N  
R30W  
S. 35

T145N  
R30W  
S. 2

B.T.

B.T.

Species J. Pine J. Pine

Diameter 6" 12"

Bearing N 47 W S 88 W

Distance 1.2chs. 11.2lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Harold Hennes

(Signature)

Mar. 18, 1937

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 1450146 R. 30

5th

Mer. A-19