

U. S. Department of Agriculture
FOREST SERVICE

CHIPPONA
NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. S. 34 Mer.
1/16 Corner common to Sections

23, and 24



Corner consists of a Metal Pipe (not) in place
State condition Capped Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	N. Pine	Aspen
Diameter	24"	6"
Bearing	S63 W.	N61 N.
Distance	90 lks.	34 lks.

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

Harold Hennas
(Signature)

Dec. 10, 1938
(Date)

(Title)