

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. S. 13 Mer.

Section Corner common to Sections
13, 14, 23, and 24

Corner consists of a Metal pipe (not) in place
State condition Capped in Cement

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

14	24	23	13
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 145 N. R. 30 W. S. 13	T. 145 N. R. 30 W. S. 14	T. 145 N. R. 30 W. S. 24	T. 145 N. R. 30 W. S. 23

Species	Tree	Tree	Tree	Tree
Diameter	4"	4"	4"	3"
Bearing	N72E	N23.5W	S33E	S12 W
Distance	33Lks.	13Lks.	15Lks.	104Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Harold Hennes

(Signature)

Dec. 9, 1936

(Date)

(Title)