

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

*posted 5/21*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 30 W S. 5 Mer.

Sec. Corner common to Sections

11, 12, 13, and 14

Corner consists of a squared scribed stake (not) in place


State condition fair

Dimensions above ground 3 ft. inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

*Earl W. Juntunen*

Signature.

*Chief Party*

Title.

1/13/21

Date.