

U. S. Department of Agriculture
FOREST SERVICE

A-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145-148 R. 80 5th Mar.

Section

Corner common to Sections

1, 2, 3, and 4

Corner consists of a Metal Cap (not) in place

State condition Surrounded by cement

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

35	2	1	36
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch map of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in feet.

	Y145N	Y145N	Y145N
	NSW	NSW	NSW
	2.2	2.1	2.25
	B.T.	B.T.	B.T.

Species J. Pine

Diameter 10"

Bearing N. 80.5 W. 88.5 E. N 80 E.

Distance 3.5ch, 42 lbs. 69 lbs. 2.25ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Harold Hennas


(Signature)

Mar 16 1917

(Date)

COMPLETED BY THE SURVEYOR

Metal Location Poster is on a Rock
tree 12 inches diameter, on the West
side of Tree
from which this Corner bears 100 ft
chains distant.
Give any further facts which will aid in finding this
Corner again.



(Make sketch of topography near Corner)

A-21
A21

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145-146 R. 30 5th Mer.
Section

Corner common to Sections

1, 2, 35, and 36

Corner consists of a Metal Cap (not) in place

State condition Surrounded by cement

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

55	2	1	36
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T145N
R30W
S.35

T145N
R30W
S.2

T145N
R30W
S.1

T146N
R30W
S.36

B.T.

B.T.

B.T.

B.T.

Species J. Pine ~~Aspen~~ J. Pine J. Pine

Diameter 10" ~~8"~~ 8" 8"

Bearing N31 W. S30.5 N. S6.5 E. N80 E.

Distance 3.35ch. 42 Lks. 69 Lks. 2.28ch.

Do you believe this to be a genuine Land Office Corner Yes

If not, why? _____

Harold Hennes

(Signature)

Mar. 16, 1957


(Date)

(T145)

Corner again. Give any further facts which will aid in finding this chains distant.

From which this Corner bears 530.5 M.

side of Tree inches diameter, on the Northeast Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

Mbr. A-21

T. 145-146 R. 30 E. 5th