

U. S. Department of Agriculture

FOREST SERVICE

P22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. 5 th. Mer.

9 1/16 Corner common to Sections

and 24

Corner consists of a Metal Cap (not) in place



State condition Good

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W. 1/16
S. 24
T. 145 N.

[Empty box for sketch]

W. 1/16
S. 24
T. 145 N.

[Empty box for sketch]

R. 30 W.

[Empty box for sketch]

R. 30 W.

[Empty box for sketch]

Species Tan. Tan.

Diameter 10" 10"

Bearing S85 E. S26 E.

Distance 47 Lks. 25 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? X

Harold Hennes

(Signature)

Dec. 14, 1938

(Date)

30

(Init)

U. S. Department of Agriculture
FOREST SERVICE

~~Shippewa~~ NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. S. 6 th. Mer.
9 1/16 Corner common to Sections

....., and 24

Corner consists of a Metal Cap (not) in place

State condition Good

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

24	24	24	24
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N. 1/16
S. 24
T. 145 N.

N. 1/16
S. 24
T. 145 N.

R. 30 W.

R. 30 W.

Species Tan. Tan.

Diameter 10" 10"

Bearing S 83 E. S 26 E.

Distance 47 Lks. 25 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Harold Hansen
(Signature)

Dec. 14, 1928
(Date)

(Title)

U. S. Department of Agriculture

FOREST SERVICE

Missouri NATIONAL FOREST CORNERS OF THE PUBLIC SURVEY

T. **145 N.** R. **30 W.** S. **11 E.**

N. 6. Corner common to Sections

....., and **24**

Corner consists of a **Metal Pipe** (not) in place



State condition **Good**

Dimensions above ground **6** inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



1/43.24
S.N.O.
S. 143°



1/43.24
S.N.O.
S. 143°



R. 307.



R. 307.

Species **Tom.** **Tom.**

Diameter **10** **18**

Bearing **S22°** **S84°**

Distance **95 lbs.** **50 lbs.**

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why?

Harold Hanson
(Signature)

Dec. 14, 1936

(Date)

(Title)