

U. S. Department of Agriculture
FOREST SERVICE

D22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 30 W. 5th Mer.
SW 1/16

Corner common to Sections

Corner consists of a Metal Pipe (not) in place

State condition Good

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

1	1	1	1
---	---	---	---

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

SW1/16
S. 1



SW1/16
S. 1



B. T.



B. T.



Species Cedar

Birch

Diameter 10"

8"

Bearing N 21

S 75 15 N

Distance 25.5 Lks.

45.5 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Lloyd Holson

(Signature)

Dec. 8, 1936

(Date)

(Title)

Metal Location Poster is on a
 three inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.




Fig. 8. (Metal location of topography near Corner)