

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. 5th Mer.

Center Section Corner common to Sections

and 34

Corner consists of a Metal Pipe (not) in place

State condition Capped

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

24	24	24	24
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. <u>34</u> S.M.C.	S. <u>34</u> S.M.C.		
T. <u>145 N.</u> R. <u>30 W.</u>			

Species Basswood Ash

Diameter 12" 4.5"

Bearing N. 127. N. 308.

Distance 7 lks. 75 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Harold Homes

(Signature)

Dec. 7, 1936

(Date)

(Title)