

U. S. Department of Agriculture
FOREST SERVICE

Shipman NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. S. 12. Mer.
8 1/16

Corner common to Sections

-----, -----, and -----

Corner consists of a Metal Pipe (not) in place

State condition Good

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

<u>24</u>	<u>24</u>	<u>24</u>	<u>24</u>
-----------	-----------	-----------	-----------

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>ON/16</u>	
<u>2.24</u>	

<u>ON/16</u>	
<u>2.24</u>	

<u>B.T.</u>	
-------------	--

<u>B.T.</u>	
-------------	--

Species Norway P. Norway Pine Stump

Diameter 14" 14"

Bearing 225 E 225 E

Distance 22.5 Lks. 20.5 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? -----

Lloyd Nelson

(Signature)

Nov. 14, 1936

(Date)

(Title)