

U. S. Department of Agriculture
FOREST SERVICE

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 20 W. S. 34 Mer.

NO Corner common to Sections

34, and 19

Corner consists of a Metal capped (not) in place

State condition Good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>34</u>		<u>19</u>

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

FLASH.
E. 30°
E. 30°



FLASH.
E 29°
E 10°



B. T.



B. T.



Species Aspen

Diameter 2"

Bearing E 10 30°

Distance 35.7 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

John Felson

Dec. 11, 1934

(Date)

(Title)

U. S. Department of Agriculture
FOREST SERVICE

~~Calypso~~ NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. ~~145 S.~~ R. ~~30 W.~~ ~~8th~~ Mer.

Corner common to Sections

~~24~~, and ~~10~~

Corner consists of a ~~Metal Cap~~ (not) in place

State condition ~~Good~~

Dimensions above ground ~~0~~ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	24		10

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

PLANT	
B. T.	
D. T.	

PLANT	
B. T.	
D. T.	

Species ~~Aspen~~ ~~Aspen~~

Diameter ~~9"~~ ~~11"~~

Bearing ~~319 30W~~ ~~8 10 15E~~

Distance ~~36.7 Lks.~~ ~~55.2 Lks.~~

Do you believe this to be a genuine Land Office Corner? ~~Yes~~

If not, why? _____

~~Lloyd Adams~~

(Signature)

~~Dec. 11, 1924~~

(Date)

(Title)

N-0-25

Form 874-9—Revised May, 1913

U. S. Department of Agriculture
FOREST SERVICE

N025

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. 5th Mer.

MC

Corner common to Sections

24 and 19

Corner consists of a Metal Capped (not) in place



State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T145N
R.30W
S.24MC



T145N
R29W
S.19MC



B.T.



B.T.



Species Aspen Aspen

Diameter 9" D.B.H. 12" D.B.H.

Bearing W19 30" S S 10 15" E

Distance 36.7 Lks. 55.8 Lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Lloyd Folsom

(Signature)

Dec. 11, 1936

(Date)

(Title)