

U. S. Department of Agriculture
FOREST SERVICE

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 20 E. 5th Mer.

22 Sec. Corner common to Sections
20, 22, and 18


Corner consists of a Metal pipe (not) in place
State condition Good

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash Ash

Diameter 12" 12"

Bearing N 21 E N 21 E

Distance 41.7 Lks. 41.5 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Lloyd Tolson

(Signature)

Dec 22, 1908

QP-25

Form 874-9—Revised May, 1918

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N, R. 30 W 5th Mer.

N1 Sec. Corner common to Sections
24, and 19

Corner consists of a Metal Pipe (not) in place
State condition Good

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	24		19
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 145N
R. 30 W
S. 24

T. 145N
R. 30 W
S. 19

B.T.

B.T.

Species Ash Ash

Diameter 10" 15"

Bearing N21W N3E

Distance 42 lks 42 lks

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Lloyd Polson

(Signature)

Dec. 11, 1936

(Date)

(Title)