

U. S. Department of Agriculture
FOREST SERVICE


Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 20 W. Mer. 8th.

Corner common to Sections 20, 21, 24, and 25

Corner consists of a Metal Cap (not) in place
State condition Good


Dimensions above ground 0 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Ash

Diameter 10" 8"

Bearing S 11 E N 35 W

Distance 20.8 Lks. 33.7 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Lloyd Tolman

(Signature)

Dec. 14, 1908

(Date)

(Title)