

2-20-21

Form 874-9—Revised May, 1918

220-21

U. S. Department of Agriculture

FOREST SERVICE

posted

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 30 W Mer. 57 E

144 Corner common to Sections

144, 145, and 146

Corner consists of a stone (not) in place

State condition Good

Dimensions above ground 7 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

7 1/2"		8 1/2"	
7 1/2"		8 1/2"	
N	W	S	E

NW	SW	SE	NE

Mound of 2 is located 0

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

7 1/2" N 30 W 2 1/2" N 10 W			
7 1/2"			

Species Cedar

Diameter 5"

Bearing N 57 W

Distance 4 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

(Date)

(Title)