

U. S. Department of Agriculture  
FOREST SERVICE

*Pat 2*  
*L 9*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145 N.* R. *31 W.* *5<sup>th</sup>* Mer.

*Quarter* Corner common to Sections  
*16*, and *17*

Corner consists of an *Oak Post* (~~not~~) in place

State condition *Good*

Dimensions above ground *3 Ft.* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *(Old Gov. P.T.s)* *N. Pine* *S. Pine* *(New Gov. P.T.s)* *J. Pine* *J. Pine*

Diameter *1 1/4"* *1"* *5"* *6"*

Bearing *S. 56° E.* *N. 42° W.* *N. 12° E.* *N. 54° 30' W.*

*40s.* Distance *22* *24* *85.8* *50.3*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*J. A. Gjelhaug*  
(Signature)

*Tech. Eng.*  
(Title)

*12/14/34*  
(Date)

Series of horizontal dashed lines for writing.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 145 N. R. 31 W. 5th Mer.