

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

*Copied
Posted
5/36*

113

NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 145 R. 31 Mer. 5

Corner common to Sections

27, 28, 33, and 34

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____


(Signature) _____

(Date) _____

(Title) _____

12" Jack pine F scribed
12" Jack pine S F scribed
Corner again.

Metal Location Pester is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)