

U. S. Department of Agriculture

FOREST SERVICE

posted N 5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *146 N* R. *25 W* *5* Mer.

Section Corner common to Sections
17, 18, 19, and 20

Corner consists of a *stake* (not) in place
State condition *good*

Dimensions above ground *4* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

<i>5</i>	<i>5</i>	<i>5</i>	<i>5</i>
<i>18</i>	<i>19</i>	<i>20</i>	<i>17</i>
NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter *one 1/2 inch*

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Karl G. Hobes

(Signature)

Estimator

(Title)


12-11-33

(Date)

Corner again.
On telephone pole
about 100 feet
east of corner
stands by roadside. Mailbox
next to state
road junction

Give any further facts which will aid in finding this
obvious distant
from which this Corner bears
side of
tree 9 inches diameter, on the

Metal Location Poster is on a telephone pole



(Make sketch of topography near Corner)